Paint In-Filling



Paint In-filling

To fill your brass / aluminium signs with a paint in-fill is a very simple procedure.

Place your engraved brass, engraving face up on a yellow pages book.

Apply colour filling paint to the surface of the brass.

Use the small Paint Spreader to drag the paint across the surface of the engraving. You will see the paint infilling the engraving. Once filled leave the paint to dry for approx 30 minutes.

Apply some cellulose paint thinners to the top page of the yellow pages.

Place your engraved plate face down on the yellow pages and drag towards yourself. You will see excess paint being left behind. Clean off the remaining paint with a brass cleaner.

Colour filling paints, thinners and paint spreaders are all shown in the catalogue.









